

## Air joint list

Number of Ports (Min. Passage Area)	External Options	Kit Model			● = Available Option					Applicable bracket (sold sept.)
		Option Symbol	Master Cylinder (Robot Side)	Tool Adapter (Tool Side)	3kg	7kg	12kg	25kg	50kg	
					KWRY 0010	KWR 0070	KWR 0120	KWR 0250	KWR 0500	
3 Ports (Equal to $\phi 6 \times 1$ port) (Equal to $\phi 2 \times 2$ por)	Air Joint (Able to extend electrodes Resin Connector/Solder Terminal with Cable)	R	SWLZ0R0-M	SWLZ0R0-T	●	●	●	●	●	-
4 Ports (Equal to $\phi 1.6$ )	Air Joint (Able to extend electrodes Resin Connector/Solder Terminal with Cable)	P	SWLZ0P0-M	SWLZ0P0-T		●	●	●	●	-
2 Ports (Equal to $\phi 4$ )	Air Joint	Q	SWLZ0Q0-M	SWLZ0Q0-T				●	●	SWRZ0Z0